

VEHICLE PARTICULARS

JOB CARD DETAILS

Reg No. KBX004L **VIN** MCU35RAWAGKW **Year** 2005
Make TOYOTA **Model** HARRIER **CC** 2400CC/2.4L
Fuel Type Petrol **Mileage** 114118

Job Card JCLMR019280
Date 26-08-2019 **Time** 03:48 PM
Technician David Njeru

54 CHECKED - OK

0 REQUIRES FUTURE ATTENTION

5 REQUIRES IMMEDIATE ATTENTION

1 Tyres

Description	MM	Status	Remarks
FRONT LEFT	1.5		Normal
FRONT RIGHT	1.5		Normal
REAR LEFT	8.5		Normal
REAR RIGHT	8.5		Normal
SPARE TYRE 1			
SPARE TYRE 2			

2 Brakes Pads & Brake Discs

Brakes Pads			Brake Discs		
Description	Status	Remarks	Description	Status	Remarks
FRONT LEFT		Normal	FRONT LEFT		Normal
FRONT RIGHT		Normal	FRONT RIGHT		Normal
REAR LEFT		Normal	REAR LEFT		Normal
REAR RIGHT		Normal	REAR RIGHT		Normal

3 Engine Preventative Maintenance

Description	Status	Remarks	Description	Status	Remarks
ENGINE OIL LEVEL		Ok	COOLANT LEVEL		Ok
CONDITION OF OIL		Ok	SPARK PLUGS		Good
OIL LEAK		No	AIR FILTER		Good
LAST OIL CHANGE (KM)		109,472 KM	BRAKE FUIILD LEVEL		Ok
WITHIN 5000KM			WASHER FLUID LEVEL		Ok

4 Suspension

Shock Absorber			Coil Spring		
Description	Status	Remarks	Description	Status	Remarks
FRONT LEFT		Normal	FRONT LEFT		Normal
FRONT RIGHT		Normal	FRONT RIGHT		Normal
REAR LEFT		Normal	REAR LEFT		Normal
REAR RIGHT		Normal	REAR RIGHT		Normal

5 Battery

Description	Status	Remarks
VOLTAGE		12.45V
CHARGING VOLTAGE		14.01V
REPLACE NOW		No

6 Lights, Safety & Emergency, Windshield

Dashboard Lights		Parking		Indicator		Reverse		Brake	
Description	Status	Description	Status	Description	Status	Description	Status	Description	Status
ENGINE		FRONT LEFT		FRONT LEFT		FRONT LEFT		FRONT LEFT	
ABS/HANDBRAKE		FRONT RIGHT		FRONT RIGHT		FRONT RIGHT		FRONT RIGHT	
VHS/TRANCTION CONTROL		REAR LEFT		REAR LEFT		REAR LEFT		REAR LEFT	
BATTERY		REAR RIGHT		REAR RIGHT		REAR RIGHT		REAR RIGHT	

Safety	Status	Emergency Items	Status
FIRST AID KIT		BOOSTER CABLES	
FIRE		TOW BELT	
SAFETY TRIANGLE		AIR COMPRESSOR	

Comments
 Replace front tyres worn and punctures are irreparable

The 60 Point Inspection Report is intended solely as a visual evaluation of components inspected at the time and date of examination. There are no implied or expressed warranties or guarantees of any kind in connection with this vehicle inspection report.